



# BB 'Left,Down,In': Left 20mm, Down 20mm, In 60mm


WL G=0, C=0, P=0; Field=(20, 20)mm (shifts=((0, 0, 0), (20, -20, 60))); BB=5mm @ left=19.00, in=-60.00, up=-20.00; Gantry tilt=0, Gantry sag=0.dcm



WL G=90, C=0, P=0; Field=(20, 20)mm (shifts=((0, 0, 0), (20, -20, 60))); BB=5mm @ left=19.00, in=-60.00, up=-20.00; Gantry tilt=0, Gantry sag=0.dcm



WL G=180, C=0, P=0; Field=(20, 20)mm (shifts=((0, 0, 0), (20, -20, 60))); BB=5mm @ left=19.00, in=-60.00, up=-20.00; Gantry tilt=0, Gantry sag=0.dcm



WL G=270, C=0, P=0; Field=(20, 20)mm (shifts=((0, 0, 0), (20, -20, 60))); BB=5mm @ left=19.00, in=-60.00, up=-20.00; Gantry tilt=0, Gantry sag=0.dcm

